

動力刀異音 Abnormal sound at driven tool

1. 刀塔撞車後造成刀盤與齒輪頭中心位置偏移。

Centers of the tool disc and gearhead are off-position because of crash.

2. 確認刀塔端及動力刀座耦合齒是否受損？

Confirm whether the couplings on turret and driven tool holder are intact without damage?

3. 確認齒輪頭空轉時是否有異音？

Check whether there is any abnormal sound when the gearhead is idle run?

4. 動力馬達連軸器的距離是否調整錯誤？

Confirm whether tool drive motor coupling distance is adjusted correctly or not ?

5. 確認刀盤結合面或耦合機構有鐵削異物？


Confirm whether there are any metal chips on the tool disc joint surface or coupling mechanism?

6. 齒輪頭長時間使用造成零件磨損。

Confirm whether gearhead parts are worn out because of long time use ?


7. 檢查動力刀座是否受損？

Check if driven tool holder is damaged ?



圖示(一):


齒輪頭耦合齒在原點狀態下才可作換刀及旋轉之動作



Tool drive in zero - position.
Rotating or indexing is possible.

圖示(二):


齒輪頭耦合齒沒在原點狀態下不可作換刀及旋轉之動作



Tool drive not in zero - position.
Rotating or indexing is not possible.

圖示(三):

齒輪頭耦合齒在原點狀態下，但齒輪頭位移不可作換刀及旋轉之動作



Fault case.
Turret in inter position.

刀座耦合齒示意圖



齒輪頭耦合齒必須與刀盤孔同心並和導軌成平行

Only do indexing and rotating when gear head coupling is at zero position.

